				6R000100060008- 25X1	1
				23/(1	FIC
		<u> </u>	SECRET	25X1	2 5 0
		CENTRAL INTELL	LICENCE ACENON		
COUNTRY		INFORMATIO	ON REPOR	T	2
COUNTRY	Rumania			REPORT N	0
SUBJECT	Production of Wa	ar Gases in Rumania		RE	SPONSIVE TO
				1	2
X1PLACE ACOL	ЦRED	25X1		CD NO.	
	」			ORR NO.	-
				DAS NO.	
DATE ACQUI	RED			OCI NO.	
L	-				
DATE (OF I	NFO.)			DATE DIS	rr. 4 DEC 1953
	THIS DOCUMENT CONTAINS	INFORMATION AFFECTING THE NATION	AL DEFENSE	NO. OF PA	AGES 1
		WITHIN THE MEANING OF TITLE 18. SEC DDE. AS AMENDED. ITS TRANSMISSION		NO. OF EN	ICLS.
	LATION OF ITS CONTENTS Prohibited by LAW, The	TO OR RECEIPT BY AN UNAUTHORIZED REPRODUCTION OF THIS REPORT IS PR	PERSON IS	o. u.	·
1	10 11 May 10 100mg/s - May 1			SUPP. TO	
	THIS IS UNI	EVALUATED INFORMATION	ON	REPORT NO).
•					
۵				4	
	-				
1.	There is a factor	ry two km south of 1	Deva, called F	olychim Fabrica	, which is
1.	supposed to make	shoe polish, metal	scouring prod	Colychim Fabrica ucts and insect	, which is icides, but is
1.	supposed to make	ry two km south of l shoe polish, metal n producing war gas	scouring prod	Polychim Fabrica aucts and insect	, which is icides, but is
2.	supposed to make really engaged in The factory is a	shoe polish, metal n producing war gase branch of the Sovre	.scouring prodes. omchim and has	ucts and insect	icides, but is
	supposed to make really engaged in The factory is a a Soviet engineer	shoe polish, metal n producing war gase branch of the Sovre r named Stepanov.	scouring prodes. omchim and has The leading Ru	ucts and insect some 350 worke	icides, but is
	supposed to make really engaged in The factory is a a Soviet engineer	shoe polish, metal n producing war gase	scouring prodes. omchim and has The leading Ru	ucts and insect some 350 worke	icides, but is
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under h	shoe polish, metal n producing war gase branch of the Sovre r named <u>Stepanov</u> . I	scouring prodes. omenim and has The leading Ru asile and Gri	some 350 worke manian director gore Bitunzky.	icides, but is rs. The head is is Dumitru
	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under h	shoe polish, metal n producing war gase branch of the Sovre r named <u>Stepanov</u> . I nim are engineers Va to make contact with	scouring prodes. Omehim and has The leading Ru asile and Gri	some 350 worke manian director gore Bitunzky.	icides, but is rs. The head is is Dumitru
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under h	shoe polish, metal n producing war gase branch of the Sovre r named <u>Stepanov</u> . I	scouring prodes. Omehim and has The leading Ru asile and Gri	some 350 worke manian director gore Bitunzky.	icides, but is rs. The head is is Dumitru
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under had it is difficult to following data of Section 1 makes x	shoe polish, metal n producing war gase branch of the Sovrer named <u>Stepanov</u> . I him are engineers Vato make contact with on products was secuylyl bromide, bromos	scouring prodes. Omehim and has The leading Ru asile and Gri n persons work ured:	some 350 worke manian director gore Bitunzky.	rs. The head is is Dumitru
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under had it is difficult to following data of Section 1 makes x brometic	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers Vato make contact with on products was secuylyl bromide, bromos nylacetone and chold	scouring prodes. omchim and has The leading Ru asile and Gri a persons work ared: acetome, bromet	some 350 worke manian director gore Bitunzky.	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under had it is difficult to following data of Section 1 makes x brometi Section 2 makes d	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers Vato make contact with on products was securely bromide, bromos hylacetone and chold the phenylaminechlorar	scouring prodes. omchim and has The leading Ru asile and Gri a persons work ared: acetome, bromet	some 350 worke manian director gore Bitunzky.	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a section 1 makes x bromet; Section 2 makes d Section 3 makes a	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers vato make contact with on products was securylyl bromide, bromos hylacetone and chold iphenylaminechlorar unknown products.	scouring prodes. omchim and has The leading Ru asile and Gri n persons work ared: acetome, bromet bactomephenone sine, diphenyl	some 350 worke manian director gore Bitunzky. Sing in the plan hylmethylcheton cyanarsine and directors	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have defined the following data of Section 1 makes x bromet; Section 2 makes described Section 3 makes a Section 4 makes of Section 4 makes of Section 4 makes of Section 5 makes a Section 6 makes a Section 6 makes a Section 7 makes a Section 8 makes a Section 8 makes a Section 9 mak	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers vato make contact with on products was securylyl bromide, bromos hylacetone and chole iphenylaminechlorar inknown products.	scouring prodes. Omchim and has The leading Ruasile and Grin persons work ared: acetone, bromet bactonephenone sine, diphenyl and chlorpicri	some 350 worke manian director gore Bitunzky. Sing in the plan hylmethylcheton cyanarsine and directors	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have defined the following data of Section 1 makes x bromet; Section 2 makes described Section 3 makes a Section 4 makes of Section 4 makes of Section 4 makes of Section 5 makes a Section 6 makes a Section 6 makes a Section 7 makes a Section 8 makes a Section 8 makes a Section 9 mak	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers vato make contact with on products was securylyl bromide, bromos hylacetone and chold iphenylaminechlorar unknown products.	scouring prodes. Omchim and has The leading Ruasile and Grin persons work ared: acetone, bromet bactonephenone sine, diphenyl and chlorpicri	some 350 worke manian director gore Bitunzky. Sing in the plan hylmethylcheton cyanarsine and directors	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a soviet engineer following data of Section 1 makes a bromet Section 2 makes described 3 makes a Section 4 makes a Section 5 probable	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers vato make contact with on products was securylyl bromide, bromos hylacetone and chole iphenylaminechlorar inknown products.	scouring prodes. Omchim and has The leading Russile and Grin persons work ared: acetone, bromet cactonephenone sine, diphenyland chlorpicrical.	some 350 worke manian director gore <u>Bitunzky</u> . Sing in the plan hylmethylcheton cyanarsine and director	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a soviet engineer following data of Section 1 makes a bromet Section 2 makes described 3 makes a Section 4 makes a Section 5 probable	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. In the stepanov of the stepanov o	scouring prodes. Omchim and has The leading Russile and Grin persons work ared: acetone, bromet cactonephenone sine, diphenyland chlorpicrical.	some 350 worke manian director gore <u>Bitunzky</u> . Sing in the plan hylmethylcheton cyanarsine and director	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a soviet engineer following data of Section 1 makes a bromet Section 2 makes described 3 makes a Section 4 makes a Section 5 probable	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. In the stepanov of the stepanov o	scouring prodes. Omchim and has The leading Russile and Grin persons work ared: acetone, bromet cactonephenone sine, diphenyland chlorpicrical.	some 350 worke manian director gore <u>Bitunzky</u> . Sing in the plan hylmethylcheton cyanarsine and director	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a soviet engineer following data of Section 1 makes a bromet Section 2 makes described 3 makes a Section 4 makes a Section 5 probable	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I mim are engineers verto make contact with on products was seen ylyl bromide, bromos hylacetone and chold iphenylaminechlorar inknown products. Schlorine, phosgene aly makes mustard gas buld be secured about	scouring prodes. Omchim and has The leading Russile and Grin persons work ared: acetone, bromet cactonephenone sine, diphenyland chlorpicrical.	some 350 worke manian director gore <u>Bitunzky</u> . Sing in the plan hylmethylcheton cyanarsine and director	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a soviet engineer following data of Section 1 makes a bromet Section 2 makes described 3 makes a Section 4 makes a Section 5 probable	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I nim are engineers Vatto make contact with on products was securlylyl bromide, bromos hylacetone and chold iphenylaminechlorar unknown products. Chlorine, phosgene ally makes mustard gas buld be secured about	scouring prodes. omehim and has The leading Ruasile and Grin persons work wred: acetome, bromet bactonephenone sine, diphenyl and chlorpicrical action of the production of	some 350 worke manian director gore <u>Bitunzky</u> . Sing in the plan hylmethylcheton cyanarsine and director	rs. The head is is Dumitru t, but the
2.	supposed to make really engaged in The factory is a a Soviet engineer Mocioran; under have a soviet engineer following data of Section 1 makes a bromet Section 2 makes described 3 makes a Section 4 makes a Section 5 probable	shoe polish, metal n producing war gase branch of the Sovrer named Stepanov. I nim are engineers Vatto make contact with on products was securlylyl bromide, bromos hylacetone and chold iphenylaminechlorar unknown products. Chlorine, phosgene ally makes mustard gas buld be secured about	scouring prodes. Omchim and has The leading Ruasile and Grin persons work ared: acetone, bromet bactonephenone sine, diphenyl and chlorpicrical are production of the production of the second production of the production of the second production	some 350 worke manian director gore <u>Bitunzky</u> . Sing in the plan hylmethylcheton cyanarsine and director	rs. The head is is Dumitru t, but the

Approved For Release 2003/08/05 : CIA-RDP81-01036R000100060008-7

SECRET

FBI

OSI EV

ORR EV

25X1

25X1

DISTRIBUTION - STATE

ARMY

NAVY